




Enter a new Standard as User table




Choose MENU of measurement menu




Choose USER TABLES




Choose S/cm Standards




Freely choose one of the user tables



Choose the resolution and unit for the table values




Select the value at 25°C




electrochemical analyser

Enter the value at 25°C (OK + arrows to set)



electrochemical analyser

Enter also the values at the other temperatures



electrochemical analyser

Press MODE when the table is filled



electrochemical analyser

In the calibration menu, choose the user table value at 25°C as the table to use for the calibration